

## # 10-Ind-01

Date: Thursday, March 11, 2010

To: Lumenera Partners

From: Darren Bessette, Industrial Product Manager



## Re: <u>Lu120 & Lu125 Product Modification Notice</u> <u>#10-Ind-01</u>

A manufacturer modification to the CMOS sensor designed into the Lu120 and Lu125 USB 2.0 camera models has resulted in a change to the sensor and Lumenera part ordering numbers. Effective immediately the part numbers for these products will change as follows:

Camera Description	Previous Part Number	New Part Number
1.3 megapixel, color, USB 2.0 board level camera module	Lu120C	Lu120CB
1.3 megapixel, monochrome, USB 2.0 board level camera module	Lu120M	Lu120MB
1.3 megapixel, color, USB 2.0 enclosed camera	Lu125C	Lu125CB
1.3 megapixel, monochrome, USB 2.0 enclosed camera	Lu125M	Lu125MB

Although camera functionality and specifications have not changed with this product modification, we have identified some subtle differences in the behavior of the replacement sensor you should be aware of. Please take a moment to read over the attached "Sensor Obsolescence Technical Brief" that explains these minor differences.

We have secured some quantities of the original sensor that will be consumed with existing orders. Once the stock is depleted, new orders will be automatically switched over to the new part number.

If there are any immediate questions or concerns, please contact your Business Development Representative at +1-613-736-4077/<u>sales@lumenera.com</u>, or our Technical Assistance Center at <u>support@lumenera.com</u>.

Lumenera Corporation • 7 Capella Court, Ottawa, ON, Canada K2E 8A7 • (t) 1.613.736.4077 • (f) 1.613.736.4071 • www.lumenera.com